

Dolphin Yachts S.L. Club de Mar 07015 Palma de Mallorca info@dolphin-yachts.com Spain



# Jongert 24 DSP

Fabricant: Longueur hors tout: 28.60m (93'8") Jongert Modèle: 24 DSP Largeur: 6.50m (21'3")

Année: 1984 Tirant d'eau: 3.40m (11'2")

Matériau de la coque: Acier Carburant: 6.000 Litres

Aménagement: 8 berths in 3 cabins 3.500 Litres Eau:

Doug Peterson/Peter Sijm Architecte: 1 x 320hp Mercedes Moteurs:

Déplacement: 96 tons

795.000 € TVA exempté

Tel: +34 971 700844 Fax: +34 971 702275 Mobile: +34 609 622313

www.dolphin-yachts.com

# Dolphin Yachts S.L.

Tel: +34 971 700844

Web: www.dolphin-yachts.com



#### **MOTEURS:**

1 x 320hp Mercedes

Nombre d'heures: 13000 aprox.

#### VITESSE:

10 knots aprox.

#### **AUTONOMIE:**

2700 nautical miles

## CAPACITÉ DES RESERVOIRS:

Carburant: 6000 Litres

Eau: 3500 Litres Eaux usées: 2000 Litres

## **ÉQUIPEMENTS MÉCANIQUES:**

Cruising speed 8,5-9 knots (consumption 15-20 litre/hour)

Custom Schaffran propeller & one spare

Hydraulic 50hp bowthruster

HEM 250 litres/h watermaker (serviced 2013/14)

Condaria air conditioning, reverse cycle with three compressors (one new 2010)

Northern Lights generator 38kW/220-280V

Kohler generator 28kW/220-380V

Victron inverters (x2, 2010)

Sonnenschein Drycell batteries in two banks, 3.200 Amp

Victron battery chargers 380V + 220V (3)

Shore power connection 380V + 220V

## AMÉNAGEMENT:

Berths: 8 Cabins: 3 Head: 3

Crew Berths: 4 Crew Cabins: 2

Private stairs from the deck saloon lead to the spacious, full beam, aft master cabin with two + one berths, shower/toilet, bath & bidet

The amidships lower saloon area features a large and bright dining area for eight to ten guests and a bar overlooking the well-equipped galley with ample storage for long passages

Two double guest cabins (with an additional berth), both en-suite with shower/toilet, have also separate access aft from the saloon

Forward, the independent and practical crew area contains of two cabins, shower/toilet and a crew mess

## **EQUIPMENTS D'AMÉNAGEMENT:**

Satellite TV throughout in all cabins and saloon

CD-Stereo throughout in all cabins

## CARRÉ:

Fridge (three compressors, one new (2010), additional vegetable fridge in bilge)

Deep-freezer (serviced 2010)

Sharp microwave oven

Miele coffee machine

Miele stove

Miele steamer

Miele dishwasher

Miele washing machine

## Dolphin Yachts S.L.

Tel: +34 971 700844

Web: www.dolphin-yachts.com



## Miele dryer

#### **NAVIGATION:**

All new navigation equipment 2010/2012

Simrad autopilot

Simrad AR 78+AP50 Gyro compass

GPS/Plotter - Philips GPS, Furuno GP 32 (new 2012 / MAXSEA 10/7, new 2010)

Simrad 48nm radar

Furuno Navtex receiver NX-500

Wempe barograph

**B&G** sumlog

B&G wind speed & direction

B&G close hauled & running

VDO rudder angle indicator

Simrad RS 35 VHF plus AIS

Skanti 8000 200 W SSB installed (without transmitter antenna)

Inmarsat C SatCom

#### PONT:

All Lewmar self-tailing winches (2x 90 ST hydraulic 3-speed, 2x 70 ST electric 3-speed, 5x 55 ST manual, 3x 48 ST manual, 2x 46 ST manual, 1x 43 ST manual, 1x 55 ST electric)

Anchor windlass

Anchor & chain (2)

Deck wash system

Jongert bathing platform and ladder

#### **VOILES:**

Rondal masts, in-mast furling Rondal booms Rondal electro-hydraulically operated roller-furling Main, mizzen, staysail, genoa and MPS - all sails by Quantum (new 2008/09)

## SÉCURITÉ:

Life rafts (2x 8 man BFA)

Life jackets (10 + one / CO2 inflatable)

Life belts

ACR EPIRB

Bilge alarm

Fire-extinguishers in engine room and all cabins

#### **CANOTS/JOUETS:**

AB 3.20m dinghy with Yamaha 15hp

Bauer Capitano diving compressor

## HISTOIRE SERVICE ET CONSTRUCTION:

## Refit 2012:

Superstructure and topsides repainted in blue

New carpets in saloon, guest cabins and crew quarters

New Daarlderop boiler aft

Shaft coupling

Fresh water tank opened, cleaned out and primed

Two plates replaced at water tank

Hull sandblasted, primed and finished with three coats of antifouling

Anchor windlass overhauled

Anchor chain galvanized

Both anchors galvanized

#### Refit 2008:

# Dolphin Yachts S.L.

Tel: +34 971 700844

Web: www.dolphin-yachts.com



Replaced one Daarlderop boiler forward

Toilet system completely re-plumbed

All grey and black water tanks opened, cleaned and sandblasted

Painted and replaced six plates

Replaced plates in the bow

New Quantum sails: mizzen, main, staysail, jib (Dacron)

Deck sanded throughout

Replaced black tank pump

Replaced bilge pump

Replaced fresh water pump

Replaced two battery chargers

Overhauled bowthruster

#### Refit 2006:

Galley refit (all appliances by Miele): oven, dishwasher, dryer, washing machine, coffee machine, steamer, new granite counter throughout

Bathroom refit throughout: granite counters, showers, light fitting, faucets

Navigation station refit: B&G H3000, Simrad autopilot, Simrad 48nm radar, Simrad AR 78 Gyro

repeater, Sanshin HR 1012 remote control search light

Satellite TV in all cabins and saloon

Rondal roller furling system replaced: forestay with foil, inner forestay with foil

Complete set of new battery banks (1600 Amp hrs and 1400 Amp hrs)

#### COMMENTAIRE DU COURTIER:

This truly classic **Jongert 24 DSP** is an outstanding example of a semi-custom-built ketch by Doug Peterson, with the interior design by Peter Sijm. Thanks to her superior build quality, large volume and easy sail handling systems, the yacht suits perfectly for long voyages in safety and comfort, offering accommodation for up to eight guests, plus four crew.

The enclosed deck house, with ample comfortable seating, provides shelter in all climate zones, and her generous outside cockpit offers plenty of space for eight quests.

She has constantly been upgraded and improved since new, having had her last refit in 2012, and is ready to go. GREAT OPPORTUNITY!!

## **EMPLACEMENT:**

Spain















# Dolphin Yachts S.L. Tel: +34 971 700844

Web: www.dolphin-yachts.com



Les informations présentées dans cette brochure sont probablement correctes mais leur exactitude n'est pas garantie et ne pourra pas être utilisée pour un contrat. Une expertise Independent est toujours recommandée. Ce bateau peut être retiré de la vente sans préavis.