



# Dolphin Yachts

INTERNATIONAL YACHT BROKERS

Dolphin Yachts S.L.

Club de Mar

07015 Palma de Mallorca

Spain

info@dolphin-yachts.com

---

## Oyster 68

Производитель:	Oyster	Длина:	20.57m (67'5")
Модель:	68	Ширина:	5.26m (17'3")
Год выпуска:	1989	Осадка:	2.36m (7'7")
Материал:	Стеклопластик	Топливо:	2 tons
Размещение:	10 berths in 5 cabins	Вода:	2 tons
Дизайнер:	Holman & Pie	Двигатели:	1 x 160hp Perkins
Водоизмещение:	39462 kg	Киль:	Wing

375.000 € НДС не уплачен



## Двигатели:

1 x 160hp Perkins 6354T

## Вместимость:

Топливный бак: 2 tons

Бак пресной воды: 2 tons

## Механическое оборудование:

Hydraulic Bow thruster

Water maker not serviced

Generator serviced, (5 years old)

Grey and black water tank automatic and manual controlled

## Размещение:

Berths: 10

Cabins: 5

Head: 5

Crew Berths: 1

Crew Cabins: 1

Large owner's cabin, two further ensuite double cabins, an upper and lower berth cabin and separate crew accommodation forward.

The main saloon is spacious and light with seating to port with a coffee table and aft of this is a dining table with seating for ten people with flat screen TV and Alcantara upholstery.

The two double cabins are forward with the crew beyond this. Aft of the main saloon behind the large chart table is a day heads and access to a useful upper and lower birth cabin. Behind the galley is access to the owner's stateroom with a large double berth to port and seating to starboard.

## Внутреннее оборудование:

5 Air conditioning units

Plasma TV

Music throughout - separately controlled

## Камбуз / Прачечное оборудование:

2 fridges

2 freezers

Icemaker

Washing and drying machine

Hoover

## Навигационное оборудование:

Hydraulic Autopilot

B & G and Raymarine full set of electronic navigation plus wind control, depth and speed

SSB Icom Radio

2 VHF radios

Weather fax

## Оборудование палубы:

Hydraulic windlass

Hydraulic davits

Dodger and bimini (New)

Teak decks (6 Years old)

All windows and hatches resealed

## Рангоут и паруса:



All sails hydraulic furling, GENOA, Jib, Main (5 years old)  
Hydraulic Boom thruster/manual  
Mast, boom, furlers, rigging all Randall  
Hydraulic control box and buttons (all new)

#### Аварийно-спасательное оборудование:

2 liferafts

All safety equipment

#### Тендеры и водное снаряжение:

Dinghy plus two outboards

#### Ремонт и техобслуживание:

2020 - 2022:

1. Main engine full refit incl. new starter, alternator, exhaust, and the head were taken to be polished, and new gaskets everywhere.
2. The generator is 5 years old and was used only on 2 months trip to Greece in 2018.
3. Sails are 5 years old and used only on the same trip
4. Two of the 5 toilets are new, other 3 refitted
5. Of the 30 pumps onboard, 7 were refitted rest changed
6. All hydraulics refitted or changed including a new control panel inside and one outside in the cockpit.
7. Anchor winch refitted
- 8 Hydraulic pump of auto pilot new
- 9 Hydraulic pump of davits refitted
10. New dodger and bimini
11. Boom repainted
12. Teak on the deck in good condition, small recaulking done
13. Winches all serviced
14. SSB radio installed
15. New weather fax
16. New tricolor and anchor light on the top of the mast

#### Комментарии брокера:

Best five cabin layout ever seen on an Oyster 68! Quality strength performance and a design well ahead of her time.

#### Местонахождение:

Spain



Все представленные выше данные основаны на информации, предоставленной продавцами. Данная информация считается достоверной, однако мы не несем ответственности за ее точность. Потенциальному покупателю настоятельно рекомендуется самостоятельно проверить предоставленную информацию и воспользоваться услугами квалифицированного морского эксперта и / или произвести проверку двигателей. В том случае, если проверка двигателей будет произведена нашей компанией, это не влечет никакой ответственности с нашей стороны.